

AI-03807 Colorado 90K Service

Owner	Ⓜ Rigel Arcayan
Tags	Problem
Created time	May 10, 2026 8:57 AM

A 2009 Chevy Colorado Crew Cab V8, Miles-90,687 miles went in for a 90k service

Service Invoice Summary: RO #40810

1. **90K Look Over / Check Belts / Fluids / Brakes / Suspension:** \$0.00
2. **Tire Light On (Sensor Programming):** \$40.00
3. **Door Locks Inop / Keyless Entry Cover:** \$29.51
4. **Remove & Replace Valve Cover Gaskets & Spark Plugs:** \$576.16
5. **Remove & Replace Drive Belt:** \$90.45
6. **Rear Differential Service:** \$144.42
7. **Replace Fluid - Transfer Case:** \$114.84
8. **Replace Trans Fluid & Filter:** \$426.36
9. **Remove & Replace Differential Pinion Seal:** \$368.91
10. **Replace Front Engine Timing Cover Gasket:** \$1,536.08
11. **Remove & Replace Engine Oil Pan:** \$896.91
12. **A/C Evac, Recharge & Condenser Replacement:** \$807.41
13. **Remove & Replace Door Lock Actuators (All):** \$1,333.36
14. **BG Fuel / Air Induction Service:** \$169.11
15. **Remove & Replace Trans Oil Cooler Line:** \$334.44
16. **Wheel Alignment:** \$0.00

17. RO Fees (Shop Supplies, Hazmat, RO Fee): \$70.00

Grand Total: \$6,937.96

Based on the images provided from Long's Automotive, here is the extracted text from the invoice for your 2009 Chevrolet Colorado LT, organized by the service item numbers:

1. 90K LOOK OVER / CHECK BELTS / FLUIDS / BRAKES / SUSPENSION

- Labor: \$0.00

1. TIRE LIGHT ON

- Labor: NEW SENSOR INSTALLED BY NTB (CUSTOMER DOESNT WANT TO GO BACK). TRY PROGRAMMING (\$40.00)

1. 3 DOOR LOCKS INOP. REMOTE INSIDE CAR

- Labor: 3 DOOR LOCKS INOP. REMOTE INSIDE CAR (CUSTOMER WANTS TO KNOW IF NEW CASING NEEDED OR NEW REMOTE) (\$0.00)
- Part: Keyless Entry Transmitter Cover (\$27.26)

1. Remove & Replace Valve Cover Gaskets & spark plugs

- Labor: Remove & Replace Left and Right Valve Cover Gasket (Both Sides) & spark plugs (\$362.50)
- Parts: Engine Valve Cover Gasket Set (\$34.28), Gold Iridium Spark Plug (\$92.48), Spark Plug Wire Set (\$70.62)

1. Remove & Replace Drive Belt (Accessory/Serpentine)

- Labor: Remove & Replace Drive Belt (Accessory/Serpentine) (\$60.00)
- Part: Premium OE Micro-V Belt (\$28.13)

1. Rear Differential Service (Drain and Fill)

- Labor: Rear Differential Service (Drain and Fill) (\$66.00)
- Part: Gear Oil, GL-5 75W90 32OZ., Genuine GM Synthetic (\$72.44)

1. Replace Fluid - Transfer Case

- Labor: Replace Fluid - Transfer Case (\$55.00)
- Part: Gear Oil, 75W-80 MTL GL-4 1QT, Full Synthetic (\$55.28)

1. Replace Trans Fluid, Change

- Labor: Remove & Replace Trans Oil Pan Gasket With Skid Plate (\$290.00)
- Parts: Genuine GM Transmission Filter Kit (\$60.15), Automatic Transmission Fluid (\$65.82)

1. Remove & Replace Differential Pinion Seal

- Labor: Remove & Replace Front Differential Pinion Seal (\$261.00)
- Parts: Differential Pinion Seal (\$27.25), Gear Oil, GL-5 75W90 32OZ., Genuine GM Synthetic (\$72.44)

1. Replace Front Engine Timing Cover Gasket

- Labor: Replace Front Engine Timing Cover Gasket (\$1,450.00)
- Part: Engine Timing Cover Gasket Set (\$79.52)

1. Remove & Replace Engine Oil Pan

- Labor: Remove & Replace Engine Oil Pan 5.3L (\$725.00)
- Parts: Genuine GM Engine Oil Pan Gasket (\$70.16), ENGINE OIL FULL SYNTHETIC (\$63.54), Genuine GM Engine Oil Filter (\$10.41), Genuine GM Engine Oil Pan Cover Gasket (\$14.70)

1. A/C EVAC & RECHARGE SERVICE

- Labor: A/C EVAC & RECHARGE SERVICE (\$95.00), Replace Condenser, R&R (\$430.65)
- Parts: FREON, OIL & DYE (\$43.20), A/C Condenser (\$217.09)

1. Remove & Replace Door Lock Actuator (All)

- Labor: Remove & Replace Front Door Lock Actuator (All) (\$580.00)
- Parts: Door Lock Actuator Motor (\$338.26), Door Lock Actuator Motor (\$357.68)

1. BG Fuel / Air Induction Service BG

- Labor: BG Fuel / Air Induction Service (\$89.00)
- Parts: 44K FUEL SYSTEM CLEANER (\$28.00), AIR INTAKE VALVE & COMBUSTION CHAMBER CLEANER (\$46.00)

1. Remove & Replace Trans Oil Cooler Line

- Labor: Remove & Replace Upper and Lower Trans Oil Cooler Line (\$145.00)
- Part: Transmission Line Set (\$175.00)

1. WHEEL ALIGNMENT

- Labor: WHEEL ALIGNMENT (\$0.00)

Fees & Totals

- **RO Fees:** Shop supplies (\$40.00), Hazmat (\$25.00), R.O. FEE (\$5.00)
- **Total Labor:** \$4,649.15
- **Total Parts:** \$2,049.71
- **Total Fees:** \$70.00
- **Subtotal:** \$6,768.86
- **Taxes:** \$169.10
- **Grand Total:** \$6,937.96